

Century Machinery Co., Inc.

1937 South Santa Fe Avenue Los Angeles, Calif. 90021

(213) 627-2847 • Fax (213) 627-2499

E-Mail: sales@centurymachinery.com

WEBSITE: www.centurymachinery.com

Ref. Number M1974-10062

- Air Compressor
- C.N.C. Machine Tools
- Fabricating Equipment
- Fluid Forming Press
- Industrial Machinery
- Machine Tools
- Profilers 3 and 5 Axis
- Routers: Pin, Radial & CNC
- Sheet Metal Machinery
- Woodworking Machinery

Appraisal Service

**"WE PURCHASE
ONE MACHINE OR
ENTIRE PLANT"**

Serving Industry
Since 1934



KEARNEY & TRECKER HORIZONTAL MILLING MACHINE

Model 550TF-20, Type PLAIN, Serial Number 57-1001-13

SPECIFICATIONS:

WIDE KNEE, TWIN ELEVATING SCREW

SPINDLE:

Taper 50 MT
Speeds: 15, 18, 22, 27, 33, 41, 50, 61, 74, 90, 111, 135, 165, 201,
248, 302, 370, 448, 454, 672, 822, 1000, 1233, 1500 RPM.

TABLE: (3) T-Slots

Size Overall, W x L 19½" x 96"
Longitudinal Travel (X-Axis) 50"
Cross-Slide Travel (Y-Axis) 16"
Vertical Travel Knee (Z-Axis) 21"

TABLE FEEDS: (32)

Longitudinal and Cross 3/8" to 90 ipm
Vertical Knee 1/8" to 30 ipm
Rapid Traverse Longitudinal and Cross 150" ipm
Rapid Traverse Knee (Vertical) 50" ipm

MOTOR: Wired 460 volts, 3-phase

Horizontal Spindle 50 H.P. 230/460 volts
Table and Knee Feed 5 H.P. 230/460 volts
Power Draw Bar 5 H.P. 230/460 volts
Coolant Pump ¼ H.P. 230/460 volts

CONTROLS: Wired 110 volts

Located on Magnetic Starter Enclosure is: Master Start/Stop Buttons,
Right/Left Spindle Switch, Coolant On/Off Switch. Draw Bar In / Out Buttons,
Spindle/Draw Bar 2-position Switch Start Button.

EQUIPPED WITH: Mono-Lever and Automatic Cycle Table Control.

Positive Backlash Control: with automatic release in rapid traverse & with lockout
for manual operation.

Operator's side controls for hand & power feed for table, saddle, knee and rapid traverse.

1- Power Draw Bar. 1- Arbor Support. 1- Mill Arbor.

COMPLETE FACTORY SAFETY GUARDS

Dimensions 108" F-B x 115" L-R x 79" Approx Wt 17,500 lbs.

PLEASE EMAIL US YOUR REQUEST FOR A FORMAL QUOTATION WITH PRICE

AT sales@centurymachinery.com

Please use this inventory reference number M1974-10062

<http://www.centurymachinery.com/request form.htm>

You may view this machine at our location under power and view photo on our website: www.centurymachinery.com

Respectfully submitted,

CENTURY MACHINERY CO., INC.